

TECH BULLETIN

TEK-B5

Ford / Mercury Release Bearing & Steel Repair Sleeve Kit

Application: 88–90 Ford Escort, Tempo Taurus (incl.SHO) & Mercury Sable & Topaz w/ MTX manual trans.

Kits: 07-069, 07-078

The Problem: Excessive wear on the release bearing retainer (quill).

The Solution: Steel Retainer Sleeve that gives the release bearing a new surface to slide on.

Ford released part number F2DFZ7548 be consisting of a release bearing and steel sleeve. These parts are designed to replace the O.E. bearing and repair the damaged retainer bearing collar quill on the above mentioned applications with the MTX manual transmission.

