

# TECH BULLETIN

TEK-B11

## 1990-1996 Nissan 300ZX

### **CAUTION: Nissan Flywheel Re-Surfacing**

#### **Clutch Kits: 06-045 & 06-046**

To release system on the Nissan 300ZX does not permit for a flywheel cut of any more than .003" without causing release issues. As most normal re-surfacing exceeds this amount, the flywheel should always be replaced when installing a new clutch on this application.