

TECH BULLETIN

TEK-B7

1987-93 Ford Light Truck CRITICAL Flywheel/Disc Match

Affected Applications: 1987-93 Ford Light Trucks with 5.0 & 5.8L Engines.

Clutch Kits: 07-032, 07-057 & 07-057-WS

Prior to installation, ensure the disc damper fits into the flywheel opening with proper clearance (minimum of .070). A mismatch can cause contact between the disc damper and the inside diameter of the flywheel. Although the clutch may function properly initially, release problems will result.